




How to update firmware for TSP654II by USB Interface


1. Go to **Control Panel** choose **Devices and Printer** then right click **"Printer Properties"** at your printer need to update and select **"Port"** then uncheck **"Enable bidirectional Support"** then click **"OK"** after that restart PC or Laptop.




- Go to folder "TS65-231_TSP650II_V60-b20_201802" for update firmware... doubles click "MOT2PRINTER.exe" >> "Printer" (on top of program) >> Selected printer you need to update and choose "Invalid"





- Click "Write" >> choose file for update main only and click "Open"



4. Click "OK" 2 times.




5. Waiting for updating until finished. (During updating look at the red-light Error on the printer will flashing) then program show Write End! (When finished printer have some sound you can print self-test page for check main version)



6. Before you update boot version you need to turn off printer for change dipswitch under the printer from default change at 1 and 3 (please see below picture)



7. Turn on printer again and follow number 2 (on top) again but number 3 please change file from Main to Boot and click "OK"



8. After that follow number 3, 4 and 5 again when update finished you can print self-test page for checking version firmware mina and boot.